

MEASURING YOUR SCREENS

A Straight Width	Straight Width - This is the length of screen measured straight across
B Curve Width	Curve Width - This is the length as measured with your tape following the curve of the screen
C Curve Height	Curve Height - This the distance measured from the bottommost point (or the flat surface your screen is on) to highest point inside the curve of the screen
D Thickness/Gauge	Thickness/Gauge - How thick is the metal used on your screen or what gauge steel is it?
E Flat/Straight End?	■ Flat/Straight End - Does your screen have a flat or straight part on the end or is the curve continuous from tip to tip?
F Hole Shape/Size ————	Hole Shape/Size - Are screen holes round, rectangle, square, etc? What are the dimensions of the shape?
G Web	Web - The distance or width of metal between the holes
H Screen Length	Screen Length - The length of your screen as seen from a top view
Frame No Frame	Frame - Does your screen have a support structure?

